

LIFT STATION CHECK-UPS: THE DOCTOR IS IN

Applied Technologies, Inc.

Will Hein, P.E.

Katie Hassing, P.E.

Town of Norway Sanitary District No. 1

PJ Nolan

OCTOBER 17, 2018



THE PATIENT:

TOWN OF NORWAY SANITARY DISTRICT No. 1


Established in the 1970s to protect Wind, Waubeesee, Long, and Denoon Lakes

8.2 square mile service area

Serves a population of 6,450 and a portion of the City of Muskego

Collection system

- 34 miles of 8- to 30-inch gravity sewers
- 16 lift stations
- 5.2 miles of 4- to 10-inch force main



THE SYMPTOMS

13 lift
stations were
placed into
operation in
1977



Dry Wells

- Permit-required confined space made equipment maintenance dangerous



Past typical
design lives

RUNNING TESTS: CONDITION ASSESSMENT



Collection of data

- Performed capacity analyses, talked to Norway staff, and evaluated station buildings, equipment, and sites

Development and ranking of recommendations

Development of planning-level cost estimates for recommended improvements



STATION EVALUATION

Dry Wells

- Confined space
- Structure condition
- Equipment Condition

Wet Wells

- Confined space
- Structure condition
- Grease and odor

Generator Building

- Structure condition
- Equipment condition

STATION EVALUATION



Pumping Equipment

Flow Capacities
Maintenance Access
Condition

Piping and Valves


Condition

Electrical , Controls and Communications Equipment

Condition
Dated Technology

Site Access, Condition and Security

DESIGN LIFE ASSESSMENTS



CONDITION RANKING



Condition and Performance Rankings	
Condition	
1	Excellent
2	Slight visible degradation
3	Visible degradation
4	Integrity of component moderately compromised
5	Integrity of component severely compromised
Performance	
1	Component functioning as intended
2	In-service, but higher than expected O&M
3	In-service, but function is impaired
4	In-service, but function is highly impaired
5	Component is not functioning as intended
Performance Age Adjustment	
0-50% of design life →No adjustment	
50-75% of design life →Performance (+1)	
75-100% of design life →Performance (+2)	

		Performance				
		1	2	3	4	5
Condition	1	Regions 1 & 2 No Immediate Action				
	2					
	3	Region 3 Place Under Observation				
	4	Region 4 Mid Term Corrective Action				
	5	Region 5 Near Term Corrective Action				

PATIENT X:

LIFT STATION No. 8



Constructed in 1977

Prefabricated steel
dry well

10-inch force main

Electrical service:
240V/3ph/60Hz

2 pumps installed in
2002

70 kW generator

PHYSICAL EXAM: WET WELL



Assessment

- Entrance concrete: Good
- Interior: Unable to view
- Grating: Covered with grease and debris
- Cover underside: Significant corrosion
- Grease and odor: None

Recommendations

- Enter the wet well to assess concrete and grating
- Cover corrosion: No immediate concerns

PHYSICAL EXAM: DRY WELL



Assessment

- Entrance: Significant corrosion
- Floor: Significant corrosion
- Pumping equipment: Insufficient capacity, corrosion, poor access
- Piping and valves: Operational issues



Recommendations

- Install higher capacity pumps
- Replace with new submersible lift station and valve vault

PHYSICAL EXAM: ELECTRICAL



Electrical

- Generator: Good condition, but exceeded design life
- Replace with new station



Building

- Minor structure damage
- HVAC in good condition



Site & Security

- Drainage and access issues

PHYSICAL EXAM: CONTROLS AND COMMUNICATION



Assessment

- Control panel: End of design life
- Control devices: Control levels drift
- Flow monitoring: None installed

Recommendations

- Replace controls and panel with new station
- Install flow monitoring



LIFT STATION No. 8:






RANKINGS

Table 4-8
Lift Station No. 8
Condition and Performance Rankings

Assessment Type	Building		Station		Pumping		Valves & Piping		Generator	
	Condition	Performance	Condition	Performance	Condition	Performance	Condition	Performance	Condition	Performance
Initial	2	1	2	2	3	4	5	5	2	1
Age Adjusted	2	3	2	4	3	5	5	5	2	3

LIFT STATION No. 8: RECOMMENDED ACTIONS

Figure 4-8
Lift Station No. 8
Recommended Action Chart

		Performance				
		1	2	3	4	5
Condition	1	Regions 1 & 2 No Immediate Action		Generator 	Building 	Station 
	2					
	3	Region 3 Place Under Observation			Pumps 	
	4	Region 4 Mid Term Corrective Action				
	5	Region 5 Near Term Corrective Action			Valves and Piping 	

PRESCRIPTION: CREATING A ROADMAP

Table 1-2
Lift Station Asset Condition and Performance, Adjusted

No.	Location	Building Condition	Building Performance	Station Condition	Station Performance	Pump Condition	Pump Performance	Valve and Piping Condition	Valve and Piping Performance	Generator Condition	Generator Performance
1	S. Wind Lake Rd	2	3	3	4	2	2	2	2	1	1
2	E. Wind Lake Rd	2	3	2	4	2	2	2	2	1	1
3	Kurtz Lane	2	3	2	4	3	5	3	4	2	3
4	Sadler Drive	2	3	2	4	3	4	3	4	2	3
5	W. Wind Lake Rd	3	3	3	4	3	4	2	4	2	3
6	W. Loomis Rd	3	3	2	4	3	5	2	4	2	3
7	W. Loomis Rd	2	3	3	4	3	4	2	3	2	3
8	Hart Drive	2	3	2	4	3	5	5	5	2	3
9	Scenic View Dr	-	-	2	1	2	2	2	3	-	-
10	Iverson Road	-	-	3	4	1	1	4	5	-	-
11	North Lake Road	-	-	3	4	3	4	4	5	-	-
12	Martha Circle	2	3	2	4	3	4	2	4	2	3
14	West View Drive	2	3	4	4	3	4	3	4	2	3
15	West Loomis Rd	-	-	3	4	3	4	4	5	-	-
16	Hummingbird Dr.	-	-	2	2	2	2	3	3	-	-
17	Nordic Ridge Dr.	-	-	2	2	2	2	3	3	-	-

PRESCRIPTION: IMPLEMENTATION PHASES

Near-term

0-2 years

Critical
repairs

Mid-term

3-5 years

Less
Critical

Long-term

6-10
years

Some
remaining
useful life





Table 1-1

1. All costs are in 2017 dollars.



LIFT STATION No. 8: ON THE ROAD TO RECOVERY!

- 
- District proceeded with replacement and a new submersible lift station is currently under design
 - Construction anticipated for 2019


PROGNOSIS



Less surprises



Budgeted
improvements



A happy PJ!



Questions?

Thank you!